

CERTIFICATE OF ACCREDITATION

ACLASS Accreditation Services

2009 N. 14th Street, Suite 502, Arlington, VA 22201, 877.344.3044

This is to certify that

Clark CMM Inspection Services de Mexico
Jamie Benavides Pompa No. 925, Fraccionamiento Villas del Nogalar
Ramos Arizpe, Coahuila 25900
Mexico

has been assessed by ACLASS[®]
and meets the requirements of international standard

ISO/IEC 17025:2005

while demonstrating technical competence in the field(s) of

TESTING

Refer to the accompanying Scope(s) of Accreditation for
information regarding the types of calibrations and/or
tests/types to which this accreditation applies.

AT-1282

CERTIFICATE NUMBER



ACLASS APPROVAL



Certificate Valid: 7/5/2007-7/5/2009





SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

Clark CMM Inspection Services de Mexico
Jamie Benavides Pompa No.925, Fraccionamiento Villas del Nogalar
Ramos Arizpe, Coahuila 25900 Mexico
Jose Gil Phone: 011-54-844-490-5555

TESTING

Valid to: July 5, 2009

Certificate Number: AT-1282

I. Dimensional Inspection / Measurement

Table with 5 columns: PARAMETER/EQUIPMENT, RANGE, BEST MEASUREMENT CAPABILITY [EXPRESSED AS UNCERTAINTY(+)], REFERENCE STANDARD OR EQUIPMENT, METHOD(S). Row 1: 3-D Dimensional CMM, X=2850mm, Y=1200mm, Z=1000mm, Volumetric, 0.0255mm, 0.0079mm, 0.0084mm, 0.11mm, B & S H3000 Horizontal Arm CMM, Customer Drawing PC DMIS S/W

Notes:

- 1. Best Measurement Uncertainties (Expanded Uncertainty) are based on approximately a 95% confidence interval, using a coverage of k=2
2. This scope is part of and must be included with the Certificate of Accreditation No. AT-1282

Handwritten signature of Karl Greenway

President/CEO

